

Prestigio MultiPhone PAP5044DUO

Firmware Update Guide

FW Upgrade Guide for PAP5044DUO (via SD card).

Please note that update could be applied only for exact version v.1.0.40.
Make sure that you download proper files from our web page.

Please BACKUP all critical information before applying this upgrade.

What's needed:

- SD card
- USB-cable

Here are the steps you should perform to update your device.

1. Copy FW to root of sdcard
2. Power off device
3. Press and hold Volume up button, then press power button, wait device enter recovery mode
4. Press power button to enter to recovery menu
5. Choise apply update from sdcard (Vol- button to move. Vol+ button to select)
6. Choise update.zip from sdcard (Vol- button to move. Vol+ button to select)
7. Confirm update process (Vol- button to move. Vol+ button to select)
8. Wait when update will complete.
9. Choise restart (Vol- button to move. Vol+ button to select)